


# Sleep Time Set




No Sleep




Sleep Now




10S



30S



1Min(\*)



2Min



5Min



10Min



30Min

Note: Keep pressing the button until you hear the first beep for about 8 seconds, release the button and the scanner will enter sleep.